

Two files are required for proper installation of a driver for the Tactical USB Receiver or a Drivebay receiver with USB adapter card (denoted as Drivebay-USB). They are ezusb.sys and qcusb.inf. These files are included on the root directory of the NVG Software CD, but they may also be downloaded and placed in a directory of the users choice. The CD or directory will need to be specified during the installation procedure.

Prior to installation it must be verified that a USB 2.0 port is available in which to plug the USB cable from the receiver. Sometimes it may be necessary or maybe just useful to install a separate card in the computer to provide the USB 2.0 port. This is especially useful if the card has an internal USB 2.0 port so that any cable from a Drivebay-USB remains internal to the computer. If a separate card is used, the drivers that control the USB 2.0 port on that card should be installed prior to installing the driver for the receiver.

When the above is done/verified then install the Drivebay-USB receiver in the computer and power up the computer. Or, in the case of the standalone Tactical Receiver, power up both it and the computer.

Plug the USB cable from the receiver into the USB 2.0 port.

A small "New Hardware Found" window or maybe two will appear stating something like "Metcom USB" or maybe "Tactical USB" installing...

The "Found New Hardware Wizard" window will appear and require some interaction with the user. Click "Next"

The next window will state "This will install Metcom USB" or maybe "Tactical USB", and ask for location of installation files.

Choose "Search for a suitable driver".

Click "Next"

The next window will ask for help with location.

Check "Specify a location" if you have copied files to a directory.

Check "CD-ROM" if using the NVG Software CD.

Click "Next"

The next window (if Specify a Location was checked) will ask for a directory. (May be on a network drive.)

Click "Browse"

Browse to the directory where qcusb.inf resides. Highlight that file. Click OK

The next window should say "Wizard found driver"

Click "Next"

The next window should say "Completing Found New Hardware Wizard" and

"Quorum Metcom DSP USB Adapter" or "Quorum Tactical USB Receiver", or something close to that.

Click "Finish"

You may be able to check that the driver is installed (and that the receiver is plugged into the USB port) by checking:

Control Panel >Administrative Tools >Computer Management >Device Manager >Universal Serial Bus Controllers

Should be an entry like "Quorum Metcom DSP USB Adapter" or "Quorum Tactical USB Receiver"

Under Properties for this device, it should state that "This device is working properly".

Hereafter this driver should be automatically loaded whenever the receiver is plugged into the USB 2.0 port.